Home Report

One triangle, all angles covered

RESIDENTIAL / COMMERCIAL / PROPERTY & CONSTRUCTION

www.shepherd.co.uk





- 1. Single Survey
- 2. Energy Performance Certificate
- 3. Property Questionnaire





Scottish Single Survey



survey report on:

Property address	Caladh Phorst Stairhaven Glenluce Newton Stewart DG8 0JL
------------------	--

Customer	Tracy Powell-Chorlton

Customer address	Caladh Phorst Stairhaven Glenluce Newton Stewart DG8 0JL

Prepared by	Shepherd Chartered Surveyors
-------------	------------------------------

Date of inspection	28/02/2024



www.shepherd.co.uk

PART 1 - GENERAL

1.1 THE SURVEYORS

The Seller has engaged the Surveyors to provide the Single Survey Report and a generic Mortgage Valuation Report for Lending Purposes. The Seller has also engaged the Surveyors to provide an Energy Report in the format prescribed by the accredited Energy Company.

The Surveyors are authorised to provide a transcript or retype of the generic Mortgage Valuation Report on to Lender specific pro-forma. Transcript reports are commonly requested by Brokers and Lenders. The transcript report will be in the format required by the Lender but will contain the same information, inspection date and valuation figure as the generic Mortgage Valuation Report and the Single Survey. The Surveyors will decline any transcript request which requires the provision of information additional to the information in the Report and the generic Mortgage Valuation Report until the Seller has conditionally accepted an offer to purchase made in writing.

Once the Seller has conditionally accepted an offer to purchase made in writing, the Purchaser's lender or conveyancer may request that the Surveyors provide general comment on standard appropriate supplementary documentation. In the event of a significant amount of documentation being provided to the Surveyors, an additional fee may be incurred by the Purchaser. Any additional fee will be agreed in writing.

If information is provided to the Surveyors during the conveyancing process which materially affects the valuation stated in the Report and generic Mortgage Valuation Report, the Surveyors reserve the right to reconsider the valuation. Where the Surveyors require to amend the valuation in consequence of such information, they will issue an amended Report and generic Mortgage Valuation Report to the Seller. It is the responsibility of the Seller to ensure that the amended Report and generic Mortgage Valuation Report are transmitted to every prospective Purchaser.

The individual Surveyor will be a member of the Royal Institution of Chartered Surveyors who is competent to survey, value and report upon Residential Property¹.

If the Surveyors have had a previous business relationship within the past two years with the Seller or Seller's Agent or relative to the property, they will be obliged to indicate this by marking the adjacent box.

The Surveyors have a written complaints handling procedure. This is available from the offices of the Surveyors at the address stated.

1.2 THE REPORT

The Surveyors will not provide an amended Report on the Property, except to correct factual inaccuracies.

The Report will identify the nature and source of information relied upon in its preparation.

The Surveyor shall provide a Market Value of the Property, unless the condition of the Property is such that it would be inappropriate to do so. A final decision on whether a loan will be granted rests with the Lender who may impose retentions in line with their lending criteria. The date of condition and value of the property will be the date of inspection.

Prior to 1 December 2008, Purchasers have normally obtained their own report from their chosen Surveyor. By contrast, a Single Survey is instructed by the Seller and made available to all potential Purchasers in expectation that the successful Purchaser will have relied upon it. The Royal Institution of Chartered Surveyors rules require disclosure of any potential conflict of interest when acting for the Seller and the Purchaser in the same transaction. The Single Survey may give rise to a conflict of interest and if this is of concern to any party they are advised to seek their own independent advice.

The Report and any expressions or assessments in it are not intended as advice to the Seller or Purchaser or any other person in relation to an asking price or any other sales or marketing decisions.

Х

¹ Which shall be in accordance with the current RICS Valuation Standards (The Red Book) and RICS Rules of Conduct.

The Report is based solely on the Property and is not to be relied upon in any manner whatsoever when considering the valuation or condition of any other property.

If certain minor matters are mentioned in the Report it should not be assumed that the Property is free of other minor defects.

Neither the whole nor any part of the Report may be published in any way, reproduced or distributed by any party other than the Seller, prospective purchasers and the Purchaser and their respective professional advisers without the prior written consent of the Surveyors.

1.3 LIABILITY

The Report is prepared with the skill and care reasonably to be expected of a competent residential surveyor who is a member of the Royal Institution of Chartered Surveyors.

The Report is addressed to the Seller and was prepared in the expectation that it (or a complete copy) along with these Terms and Conditions (or a complete copy) would (or, as the case might be, would have been) be disclosed and delivered to:

- the Seller;
- any person(s) noting an interest in purchasing the Property from the Seller;
- any person(s) who make(s) (or on whose behalf is made) an offer to purchase the Property, whether or not that offer is accepted by the Seller;
- the Purchaser; and
- the professional advisers of any of these.

The Surveyors acknowledge that their duty of skill and care in relation to the Report is owed to the Seller and to the Purchaser. The Surveyors accept no responsibility or liability whatsoever in relation to the Report to persons other than the Seller and the Purchaser. The Seller and Purchaser should be aware that if a Lender seeks to rely on this Report they do so at their own risk. In particular, the Surveyors accept no responsibility or liability whatsoever to any Lender in relation to the Report. Any such Lender relies upon the Report entirely at their own risk.

1.4 GENERIC MORTGAGE VALUATION REPORT

The Surveyors undertake to the Seller that they will prepare a generic Mortgage Valuation Report, which will be issued along with the Single Survey. It is the responsibility of the Seller to ensure that the generic Mortgage Valuation Report is provided to every potential Purchaser.

1.5 TRANSCRIPT MORTGAGE VALUATION FOR LENDING PURPOSES

The Surveyors undertake that on being asked to do so by a prospective purchaser, or his/her professional advisor or Lender, they will prepare a Transcript Mortgage Valuation Report for Lending Purposes on terms and conditions to be agreed between the Surveyors and Lender and solely for the use of the Lender and upon which the Lender may rely. The decision as to whether finance will be provided is entirely a matter for the Lender. The Transcript Mortgage Valuation Report will be prepared from information contained in the Report and the generic Mortgage Valuation Report².

1.6 INTELLECTUAL PROPERTY

All intellectual property rights whatsoever (including copyright) in and to the Report, excluding the headings and rubrics, are the exclusive property of the Surveyors and shall remain their exclusive property unless

² Which shall be in accordance with the current RICS Valuation Standards (The Red Book) and RICS Rules of Conduct.

they assign the same to any other party in writing.

1.7 PAYMENT

The Surveyors are entitled to refrain from delivering the Report to anyone until the fee and other charges for it notified to the Seller have been paid. Additional fees will be charged for subsequent inspections and Reports.

1.8 CANCELLATION

The Seller will be entitled to cancel the inspection by notifying the Surveyor's office at any time before the day of the inspection.

The Surveyor will be entitled not to proceed with the inspection (and will so report promptly to the Seller) if after arriving at the property, the Surveyor concludes that it is of a type of construction of which the Surveyor has insufficient specialist knowledge to be able to provide the inspection satisfactorily. The Surveyor will also be entitled not to proceed if after arriving at the property, the surveyor concludes that the property is exempt under Part 3 of The Housing (Scotland) Act 2006 as detailed in the (Prescribed Documents) Regulations 2008. If there is a potential threat to their health or personal safety, the inspection may be postponed or cancelled, at the Surveyor's discretion.

In the case of cancellation or the inspection not proceeding, the Surveyor will refund any fees paid by the Seller for the inspection and Report, except for expenses reasonably incurred and any fee due in light of the final paragraph of this section.

In the case of cancellation by the Seller, for whatever reason, after the inspection has taken place but before a written report is issued, the Surveyor will be entitled to raise an invoice equivalent to 80% of the agreed fee.

1.9 PRECEDENCE

If there is any incompatibility between these Terms and Conditions and the Report, these Terms and Conditions take precedence.

1.10 DEFINITIONS

- the "Lender" is the party who has provided or intends or proposes to provide financial assistance to the Purchaser towards the purchase of the Property and in whose favour a standard security will be granted over the Property;
- the "Transcript Mortgage Valuation Report for Lending Purposes" means a separate report, prepared by the Surveyor, prepared from information in the Report and the generic Mortgage Valuation Report, but in a style and format required by the Lender. The Transcript Mortgage Valuation Report for Lending Purposes will be prepared with the skill and care reasonably to be expected from a surveyor who is a member of the Royal Institution of Chartered Surveyors and who is competent to survey, value and report on the Property;
- the "Generic Mortgage Valuation Report" means a separate report, prepared by the Surveyor from information in the Report but in the Surveyor's own format;
- the "Market Value" is the estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion;
- the "Property" is the property which forms the subject of the Report;
- the "Purchaser" is the person (or persons) who enters into a contract to buy the Property from the Seller;

- a "prospective Purchaser" is anyone considering buying the Property;
- the "Report" is the report, of the kind described in Part 2 of these Terms and Conditions and in the form set out in part 1 of Schedule 1 of the Housing (Scotland) Act 2006 (Prescribed Documents) Regulations 2008;
- the "Seller" is/are the proprietor(s) of the Property;
- the "Surveyor" is the author of the Report on the Property; and
- the "Surveyors" are the firm or company of which the Surveyor is an employee, director, member or partner (unless the Surveyor is not an employee, director, member or partner, when the "Surveyors" means the Surveyor) whose details are set out at the head of the Report.
- the "Energy Report" is the advice given by the accredited Energy Company, based on information collected by the Surveyor during the Inspection, and also includes an Energy Performance Certificate, in a Government approved format.

PART 2 - DESCRIPTION OF THE REPORT

2.1 THE SERVICE

The Single Survey is a Report by an independent Surveyor, prepared in an objective way regarding the condition and value of the Property on the day of the inspection, and who is a member of the Royal Institution of Chartered Surveyors. It includes an Energy Report as required by Statute and this is in the format of the accredited Energy Company. In addition, the Surveyor has agreed to supply a generic Mortgage Valuation Report.

2.2 THE INSPECTION

The Inspection is a general surface examination of those parts of the Property which are accessible: in other words, visible and readily available for examination from ground and floor levels, without risk of causing damage to the Property or injury to the Surveyor.

All references to visual inspection refer to an inspection from within the property at floor level and from ground level within the site and adjoining public areas, without the need to move any obstructions. Any references to left or right are taken facing the front of the property.

The Inspection is carried out with the Seller's permission, without causing damage to the building or contents. Furniture, stored items and insulation are not moved.

Unless identified in the report the Surveyor will assume that no harmful or hazardous materials have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

The Surveyor will not carry out an asbestos inspection, and will not be acting as an asbestos inspector in completing a Single Survey of properties that may fall within the Control of Asbestos in the Workplace Regulations. In the case of flats it will be assumed that there is a duty holder, as defined in the Regulations and that a Register of Asbestos and effective Management Plan is in place, which does not require any expenditure, or pose a significant risk to health. No enquiry of the duty holder will be made.

2.3 THE REPORT

The Report will be prepared by the Surveyor who carried out the property inspection and will describe various aspects of the property as defined by the headings of the Single Survey report with the comments

being general and unbiased. The report on the location, style and condition of the property, will be concise and will be restricted to matters that could have a material effect upon value and will omit items that, in the Surveyor's opinion, are not significant. If certain minor matters are mentioned, it should not be interpreted that the property is free of any other minor defects.

Throughout the Report, the following repair categories will be used to give an overall opinion of the state of repair and condition of the property.

- 1 <u>Category 3:</u> Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.
- 2 <u>Category 2:</u> Repairs or replacement requiring future attention, but estimates are still advised.
- 3 <u>Category 1:</u> No immediate action or repair is needed.

WARNING: If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions when the effect can be considerable.

Parts of the property, which cannot be seen or accessed, will not be reported upon and this will be stated. If the Surveyor suspects that a defect may exist within an unexposed area and which could have a material effect upon the value, he may recommend further investigation by specialist contractors.

2.4 SERVICES

Surveyors are not equipped or qualified to test the services and therefore no comment can be interpreted as implying that the design, installation and function of the services are in accordance/compliance with regulations, safety and efficiency expectations. However, comment is made where there is cause to suspect significant defects or shortcomings with the installations. No tests are made of any services or appliances.

2.5 ACCESSIBILITY

A section is included to help identify the basic information interested parties need to know to decide whether to view a property.

2.6 ENERGY REPORT

A section is included that makes provision for an Energy Report, relative to the property. The Surveyor will collect physical data from the property and provide such data in a format required by an accredited Energy Company. The Surveyor cannot of course accept liability for any advice given by the Energy Company.

2.7 VALUATION AND CONVEYANCER ISSUES

The last section of the Report contains matters considered relevant to the Conveyancer (Solicitor). It also contains the Surveyor's opinion both of the market value of the property and of the re-instatement cost, as defined below.

"Market Value" The estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein

the parties had each acted knowledgeably, prudently and without compulsion. In arriving at the opinion of the Market Value the Surveyor also makes various standard assumptions covering, for example, vacant possession; tenure and other legal considerations; contamination and hazardous materials; the condition of un-inspected parts; the right to use mains services; and the exclusion of curtains, carpets etc. from the valuation. In the case of flats, the following further assumptions are made that:

• There are rights of access and exit over all communal roadways, corridors, stairways etc. and to use

communal grounds, parking areas, and other facilities;

- There are no particularly troublesome or unusual legal restrictions;
- There is no current dispute between the occupiers of the flats or any outstanding claims or losses; and the costs of repairs to the building are shared among the co-proprietors on an equitable basis.

Any additional assumption, or any found not to apply, is reported.

"Re-instatement cost" is an estimate for insurance purposes of the current cost of rebuilding the Property in its present form unless otherwise stated. This includes the cost of rebuilding the garage and permanent outbuildings, site clearance and professional fees, but excludes VAT (except on the fees).

Sellers or prospective Purchasers may consider it prudent to instruct a reinspection and revaluation after a period of 12 weeks (or sooner if appropriate) to reflect changing circumstances in the market and/or in the physical condition of the Property.

1. Information and scope of inspection

This section tells you about the type, accommodation, neighbourhood, age and construction of the property. It also tells you about the extent of the inspection and highlights anything that the surveyor could not inspect.

All references to visual inspection refer to an inspection from within the property without moving any obstructions and externally from ground level within the site and adjoining public areas. Any references to left or right in a description of the exterior of the property refer to the view of someone standing facing that part of the property from the outside.

The inspection is carried out without causing damage to the building or its contents and without endangering the occupiers or the surveyor. Heavy furniture, stored items and insulation are not moved. Unless identified in the report the surveyor will assume that no harmful or hazardous materials or techniques have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

Services such as TV/cable connection, internet connection, swimming pools and other leisure facilities etc. will not be inspected or reported on.

Description	One and a half storey detached house.
Accommodation	Ground Floor:
	Entrance Vestibule, Hallway, Lounge, Kitchen/Dining Room, Bedroom 1, Utility Room, Bathroom with w.c. and Cloakroom with w.c.
	First/Attic Floor:
	Bedroom 2, En-suite Shower Room with w.c, Bedroom 3 and En-suite Shower Room with w.c.

173m ² or thereby (first floor accommodation with sloping
ceilings measured to 1.5m height).

Neighbourhood and location	The property is situated in the small coastal settlement of Stairhaven, and enjoys unrestricted sea views over Luce Bay to the front. The main shopping, social and educational amenities are provided in Stranraer which lies approximately 12 miles distant, and a limited range of local facilities are available in Glenluce which is about 3 miles away.
----------------------------	--

Age	The property was constructed circa 2005.
Weather	Light drizzle.

Chimney stacks	Visually inspected with the aid of binoculars where appropriate.
	The right hand chimney is of block roughcast construction with lead flashings, concrete coping and clay pot.
	There is a non-functional dummy chimney to the left. It is constructed with timber OSB with a roughcast outer finish, and has lead flashings, concrete coping and clay pot.

Roofing including roof space	Sloping roofs were visually inspected with the aid of binoculars where appropriate.
	Roof spaces were visually inspected and were entered where there was safe and reasonable access, normally defined as being from a 3m ladder within the property.
	If this is not possible, then physical access to the roof space may be taken by other means if the Surveyor deems it safe and reasonable to do so.
	The roof is pitched and slated with tiled ridging.
	A hinged ceiling hatch in one of the bedrooms provides access into the apex roof space via a wooden folding ladder. There are electric lights. The roof is of timber frame construction overlaid with sarkingboard, and there is a felt membrane beneath the slates. The attic is insulated above the ceilings.

Rainwater fittings	Visually inspected with the aid of binoculars where appropriate.
	The gutters and downpipes are formed in PVC.

Main walls	Visually inspected with the aid of binoculars where appropriate.
	Foundations and concealed parts were not exposed or inspected.
	The main walls are of timber frame construction, mostly enclosed with a block roughcast and part rendered outerleaf, and the front elevations are finished in pointed stonework. The walls incorporate perpend vents, which is a typical construction detail in timber framed buildings. Fresh air intakes on the base of the walls provide ventilation to the sub- floor areas.

Windows, external doors and joinery	Internal and external doors were opened and closed where keys were available. Random windows were opened and closed where possible.
	Doors and windows were not forced open. The windows are double glazed uPVC casements, and there are timber double glazed Velux rooflights. The external doors to the front entrance and utility room are uPVC double glazed, and the fascias, soffits and bargeboards are clad in PVC. The uPVC joinery has a woodgrain effect finish.

External decorations	Visually inspected.	
Conservatories / porches	Not applicable.	

Communal areas	Not applicable.
Garages and permanent outbuildings	Visually inspected.
	There is a detached garage with a gross internal floor area of 30m ² or thereby. The walls are of timber frame construction enclosed with a block roughcast outerleaf, and the pitched roof is slated. Vehicular access is through a roller door to the front (not tested) and there is a non-glazed uPVC personnel door to the rear. The garage has power and light. There is a small boiler cupboard, attached to the right hand gable. The walls are of brick and block roughcast construction, and the roof is slated.
Outside areas and houndaries	Visually increated

Outside areas and boundaries	visually inspected.
	The house occupies a good sized plot that is enclosed with stone dykes, timber fencing and block roughcast wall.
Ceilings	Visually inspected from floor level.

Internal walls	Visually inspected from floor level.
	Using a moisture meter, walls were randomly tested for dampness where considered appropriate.
	The internal walls and the timber stud partitions are lined with plasterboard.

Floors including sub floors	The floors are of suspended timber construction.
	It was not possible to inspect the floor surfaces due to the presence of fitted coverings in all rooms. No access was gained into the sub-floor area.

Internal joinery and kitchen fittings	Built-in cupboards were looked into but no stored items were moved.
	Kitchen units were visually inspected excluding appliances.
	The internal doors are a mix of timber panelled and timber glazed types.
	There are fitted base and wall units in the kitchen and utility room, which are on fairly modern lines.
	A timber carpeted staircase provides access to the first floor landing from the hall.

Chimney breasts and fireplaces	Visually inspected.
	No testing of the flues or fittings was carried out.
	The lounge fireplace has an open fire.
Internal decorations	Visually inspected.

Cellars	Not applicable.

Electricity	Accessible parts of the wiring were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the surveyor will state that in the report and will not turn them on.
	Mains electricity.
	The electric meter is in the garage, and the consumer unit for the house is in the utility room.

Gas	Accessible parts of the system were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the surveyor will state that in the report and will not turn them on.
	Bottled propane gas is connected to the property.


Water, plumbing, bathroom fittings	Visual inspection of the accessible pipework, water tanks, cylinders and fittings without removing any insulation.
	No tests whatsoever were carried out to the system or appliances.
	Water is assumed to be from the mains supply.
	There is a ceramic sink in the kitchen, and a stainless steel sink in the utility room.
	The sanitary fittings are on fairly modern lines and include a four piece white suite in the bathroom, a white wash hand basin and w.c. in the cloakroom/toilet and the two en-suite shower rooms have three piece white suites.

Heating and hot water	Visual inspection of the accessible pipework, water tanks, cylinders and fittings without removing any insulation.
	No tests whatsoever were carried out to the system or appliances.
	The 'Grant Combi 90 Mk II' oil fired boiler is in a small external cupboard at the side of the house. The boiler provides domestic hot water, and it also heats radiators in the main rooms. The radiators are fitted with thermostatic valves, and there is a room thermostat in the ground floor bedroom. Hot water is supplemented by electric showers (not tested) in the two en-suite shower rooms.

Drainage	Drainage covers etc. were not lifted.
	Neither drains nor drainage systems were tested.
	Drainage is understood to be connected to a septic tank. For the avoidance of doubt the tank was not located or inspected to confirm its age, type and condition, and the drainage system has not been checked or tested in any way.

Fire, smoke and burglar alarms	Visually inspected.
	No tests whatsoever were carried out to the system or appliances.
	All Scottish homes require a smoke alarm to be installed in the room most frequently used for living purposes and in every circulation space on each floor. A heat alarm also needs to be installed in each kitchen. The alarms need to be ceiling mounted and interlinked. Where there is a carbon- fuelled appliance such as a boiler, open fire or wood burner, a carbon monoxide detector is also required. We have not assessed or tested any existing equipment and it is the purchasers responsibility to confirm that the property will comply with these standards following a change of ownership.
	In the interests of security no comment is made in relation to the presence or otherwise of a burglar alarm.

Any additional limits to inspection	An inspection for Japanese Knotweed was not carried out. This is a plant which is subject to control regulation, is considered to be invasive and one which can render a property unsuitable for some mortgage lenders. It is therefore assumed that there is no Japanese Knotweed within the boundaries of the property or its neighbouring property. Identification of Japanese Knotweed is best undertaken by a specialist contractor.
	The inspection of the property was restricted by furnishings and fitted floor coverings, and no access was gained into the sub-floor areas. No access was available beneath sanitary or kitchen fittings. Internal cupboards were generally filled with storage items.



2. Condition

This section identifies problems and tells you about the urgency of any repairs by using one of the following three categories:

Category 3	Category 2	Category 1
e .		

Structural movement	
Repair category	1
Notes	There was no evidence of significant structural movement within the limitations of our inspection.

Dampness, rot and infestation	
Repair category	1
Notes	Damp meter readings were taken where considered appropriate within the property, and moisture levels were found to be within an acceptable range.

Chimney stacks	
Repair category	2
Notes	There is cracked roughcast to the non-functional dummy chimney.
	Otherwise, the chimney stacks appear to be in a reasonable state of repair within the limitations of our inspection, but chimneys can be vulnerable to defect and should be regularly maintained.

Roofing including roof space	
Repair category	2
Notes	The slaterwork is affected by delamination, and a few broken slates were noted, and there is some moss and lichen build up.

Rainwater fittings	
Repair category	1
Notes	Within the limitations of our inspection, the rainwater goods were seen to be free from significant defect.

Main walls	
Repair category	1
Notes	Some patch repairs were noted to the roughcast on the right hand gable. Some of the sub-floor vents at the rear are blocked by the access ramp.

Windows, external doors and joinery	
Repair category	2
Notes	A failed double glazed unit was noted to the front entrance door. The windows were not all fully opened or tested, and it should be appreciated that some defects may only be evident during certain weather
	conditions. Within the limitations of our inspection, no significant defects were noted. There is poor detailing to the uPVC trim adjoining the utility room window.

External decorations	
Repair category	1
Notes	Paint finished external surfaces will require redecoration on a regular basis.

Conservatories/porches	
Repair category	N/A
Notes	Not applicable.

Communal areas	
Repair category	N/A
Notes	Not applicable.

Garages and permanent outbuildings	
Repair category	1
Notes	There is old woodworm infestation to the garage roof, which has been partly constructed using reclaimed timber. The garage downpipes are not trapped, and discharge rainwater onto adjoining ground which is not an ideal arrangement.

Outside areas and boundaries	
Repair category	1
Notes	Boundary walls and fences should be regularly checked and maintained as necessary.

Ceilings	
Repair category	1
Notes	Minor cracking was noted to the ceiling plaster.
	Within the limitations of our inspection no significant defects were noted.

Internal walls	
Repair category	1
Notes	Within the limitations of our inspection no significant defects were noted.

Floors including sub-floors	
Repair category	1
Notes	Due to fitted carpets and floor coverings no detailed inspection of floors was possible, and accordingly no comment can be made on their condition.

Internal joinery and kitchen fittings	
Repair category	1
Notes	Within the limitations of our inspection no significant defects were noted.

Chimney breasts and fireplaces	
Repair category	1
Notes	All flue linings should be checked, repaired if necessary and swept prior to the open fires being reused.

Internal decorations	
Repair category	1
Notes	The property is in reasonably good decorative order.

Cellars	
Repair category	N/A
Notes	Not applicable.

Electricity	
Repair category	1
Notes	The Institution of Engineering and Technology recommends that inspections and testings are undertaken at least every five years and on a change of occupancy. It should be appreciated that only the most recently constructed or rewired properties will have installations which fully comply with IET regulations.

Gas	
Repair category	1
Notes	In the interests of safety and in light of recent regulations it would be prudent to have all gas appliances checked by a Gas Safe registered contractor.

Water, plumbing and bathroom fittings	
Repair category	1
Notes	No tests have been undertaken of the system, however within the limitations of our inspection, no significant defects were noted. No inspection has been possible to enclosed timbers beneath wet appliances and no comment has been made on the condition of unseen areas. Watertight seals will require to be regularly checked and replaced, to prevent water damage to adjoining areas.

Heating and hot water	
Repair category	1
Notes	It is assumed that the central heating system has been properly installed, updated and maintained to meet with all current regulations and standards with particular regard to fluing and ventilation requirements. Service records should be obtained and checked. In the absence of service documentation further advice should be obtained from a qualified heating engineer to ascertain the condition, efficiency, and life expectancy of the system.

Drainage	
Repair category	1
Notes	We were unable to determine the position of the septic tank/private drainage system. The location of the septic tank/soakaway and legal access/servitude rights must be confirmed with the Title Deeds. It must be confirmed that the drainage arrangements have SEPA consents.

Set out below is a summary of the condition of the property which is provided for reference only. You should refer to the previous comments for detailed information.

Structural movement	1
Dampness, rot and infestation	1
Chimney stacks	2
Roofing including roof space	2
Rainwater fittings	1
Main walls	1
Windows, external doors and joinery	2
External decorations	1
Conservatories/porches	N/A
Communal areas	N/A
Garages and permanent outbuildings	1
Outside areas and boundaries	1
Ceilings	1
Internal walls	1
Floors including sub-floors	1
Internal joinery and kitchen fittings	1
Chimney breasts and fireplaces	1
Internal decorations	1
Cellars	N/A
Electricity	1
Gas	1
Water, plumbing and bathroom fittings	1
Heating and hot water	1
Drainage	1

Category 3

Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.

Category 2

Repairs or replacement requiring future attention, but estimates are still advised.

Category 1

No immediate action or repair is needed.

Remember

The cost of repairs may influence the amount someone is prepared to pay for the property. We recommend that relevant estimates and reports are obtained in your own name.

Warning

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions where the effect can be considerable.

3. Accessibility information

Guidance notes on accessibility information

Three steps or fewer to a main entrance door of the property:

In flatted developments the 'main entrance' would be the flat's own entrance door, not the external door to the communal stair. The 'three steps or fewer' are counted from external ground level to the flat's entrance door. Wherea lift is present, the count is based on the number of steps climbed when using the lift.

Unrestricted parking within 25 metres:

For this purpose, 'Unrestricted parking' includes parking available by means of a parking permit. Restricted parking includes parking that is subject to parking restrictions, as indicated by the presence of solid yellow, red or white lines at the edge of the road or by a parking control sign, parking meters or other coin-operated machines.

1. Which floor(s) is the living accommodation on?	Ground and first/attic		ittic	
2. Are there three steps or fewer to a main entrance door of the property?	Yes	X	No	
3. Is there a lift to the main entrance door of the property?	Yes		No	X
4. Are all door openings greater than 750mm?	Yes		No	X
5. Is there a toilet on the same level as the living room and kitchen?	Yes	X	No	
6. Is there a toilet on the same level as a bedroom?	Yes	X	No	
7. Are all rooms on the same level with no internal steps or stairs?	Yes		No	X
8. Is there unrestricted parking within 25 metres of an entrance door to the building?	Yes	X	No	

4. Valuation and conveyancer issues

This section highlights information that should be checked with a solicitor or licensed conveyancer. It also gives an opinion of market value and an estimated reinstatement cost for insurance purposes.

Matters for a solicitor or licensed conveyancer

1) The assumed tenure is Absolute Ownership.

2) The road fronting the property is made up, and is assumed to be adopted by the Local Authority.

3) It is assumed that the septic tank drainage system is registered with SEPA.

4) It is assumed that all required Local Authority consents were obtained for the construction of the property. There are no subsequent alterations evident.

5) The property is close to the foreshore although there is no known liability to flooding.

Where defects or repairs have been identified within this report it is recommended that, prior to entering into any legally binding sale or purchase contract, further specialist's or contractor's advice and estimates should be obtained, to establish the implications, if any, on a potential offer to purchase or the sale price likely to be achieved for the property.

Estimated reinstatement cost for insurance purposes

For Reinstatement Cost Assessment purposes, it is recommended that the subjects be insured for a sum of not less than £470,000.

This figure is the estimate of the cost of rebuilding the premises and bears no direct relationship to current market value.

Valuation and market comments

Having considered matters, taking account of our general observations on site, we are of the opinion that the Market Value of the subjects in their present condition and with the benefit of vacant possession may be fairly stated in the sum of £400,000 (FOUR HUNDRED THOUSAND POUNDS STERLING).

Signed	<i>lan Young</i> Electronically signed :- 29/02/2024 21:28
Report author	Ian Young
Company name	J & E Shepherd Chartered Surveyors

Address	18 Castle Street Dumfries DG1 1DR
Date of report	28/02/2024



www.shepherd.co.uk

Property Address	
Address Seller's Name Date of Inspection	Caladh Phorst, Stairhaven, Glenluce, Newton Stewart, DG8 0JL Tracy Powell-Chorlton 28/02/2024
Property Details	
Property Type X House Purpose built flat	Bungalow Purpose built maisonette Converted maisonette Converted flat Tenement flat Flat over non-residential use Other (specify in General Remarks)
Property Style X Detached Back to back	Semi detached Mid terrace End terrace High rise block Low rise block Other (specify in General Remarks)
Does the surveyor believe that the p military, police?	property was built for the public sector, e. g. local authority,
Flats/Maisonettes only Floor(s) on wh	
Approximate Year of Construction	No. of units in block
Tenure	
X Absolute Ownership	Dther
Accommodation	
Number of Rooms 1 Living room 3 Bathroom(stress	
Gross Floor Area (excluding garage	s and outbuildings) 173 m² (Internal) 195 m² (External)
Residential Element (greater than 40	0%) X Yes No
Garage / Parking / Outbuildings	
X Single garage Double gar	age Parking space No garage / garage space / parking space
Available on site? X Yes] No
Permanent outbuildings:	
None.	

Construction
Walls Brick Stone Concrete X Timber frame Other (specify in General Remarks) Roof Tile X Slate Asphalt Felt Other (specify in General Remarks)
Special Risks
Has the property suffered structural movement?
If Yes, is this recent or progressive?
Is there evidence, history, or reason to anticipate subsidence, heave, landslip or flood in \Box Yes X No the immediate vicinity?
If Yes to any of the above, provide details in General Remarks.
Service Connections
Based on visual inspection only. If any services appear to be non-mains, please comment on the type and location of the supply in General Remarks
Drainage Mains X Private None Water X Mains Private None Electricity X Mains Private None Gas Mains X Private None Central Heating X Yes Partial None None None None None
Brief description of Central Heating and any non mains services:
Oil fired boiler to radiators.
Site
Apparent legal issues to be verified by the conveyancer. Please provide a brief description in General Remarks.
Rights of way Shared drives / access Garage or other amenities on separate site Shared service connections
III-defined boundaries Agricultural land included with property X Other (specify in General Remarks)
Location
Residential suburb Residential within town / city Mixed residential / commercial Shared service connections Commuter village Remote village X Isolated rural property Other (specify in General Remarks)
Planning Issues
Has the property been extended / converted / altered? Yes X No If Yes provide details in General Remarks.
Roads
Made up road Unmade road Partly completed new road Pedestrian access only X Adopted Unadopted

General Remarks

The property is situated in the small coastal settlement of Stairhaven, and enjoys unrestricted sea views over Luce Bay to the front. The main shopping, social and educational amenities are provided in Stranraer which lies approximately 12 miles distant, and a limited range of local facilities are available in Glenluce which is about 3 miles away.

At the time of inspection the property was found to be well maintained having regard to its age and character, with fittings internally on fairly modern lines. There are no significant defects evident that would affect the property's suitability as a mortgage security.

In addition to the main accommodation there is a utility room and a vestibule/study.

It is assumed that the septic tank drainage system is registered with SEPA.

It is assumed that all required Local Authority consents were obtained for the construction of the property. There are no subsequent alterations evident.

The property is close to the foreshore although there is no known liability to flooding.

Essential Repairs

None.		
Estimated cost of essential repairs	N/A]
Retention recommended?	Yes X No	
Retention amount	N/A]

Comment on Mortgageability

The property forms suitable security for mortgage purposes subject to the specific lending criteria of any mortgage provider.

Valuation		
Market value in present condition	£	400,000
Market value on completion of essential repairs	£	
Insurance reinstatement value	£	470,000
(to include the cost of total rebuilding, site clearance, professional fees, ancillary charges plus VAT)		
Is a reinspection necessary?		Yes X No

Declaration

Signed	Ian Young Electronically signed :- 29/02/2024 21:28
Surveyor's name	lan Young
Professional qualifications	MRICS
Company name	J & E Shepherd Chartered Surveyors
Address	18 Castle Street, Dumfries, DG1 1DR
Telephone	01387 264333
Email Address	dumfries@shepherd.co.uk
Date of Inspection	28/02/2024



Energy Performance Certificate



Energy Performance Certificate (EPC)

Scotland

Dwellings

CALADH PHORST, NEWTON STEWART, DG8 0JL

Dwelling type:	Detached house
Date of assessment:	28 February 2024
Date of certificate:	28 February 2024
Total floor area:	178 m ²
Primary Energy Indicator:	161 kWh/m ² /year

Reference number: Type of assessment: Approved Organisation: Main heating and fuel:


0160-2788-7120-2924-1831 RdSAP, existing dwelling Elmhurst Boiler and radiators, oil

You can use this document to:


- Compare current ratings of properties to see which are more energy efficient and environmentally friendly
- Find out how to save energy and money and also reduce CO₂ emissions by improving your home

Estimated energy costs for your home for 3 years*	£6,204	See your recommendations
Over 3 years you could save*	£591	report for more information

* based upon the cost of energy for heating, hot water, lighting and ventilation, calculated using standard assumptions



Very environmentally friendly - lower CO₂ emissions



Energy Efficiency Rating

This graph shows the current efficiency of your home, taking into account both energy efficiency and fuel costs. The higher this rating, the lower your fuel bills are likely to be.

Your current rating is band D (68). The average rating for EPCs in Scotland is band D (61).

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

Environmental Impact (CO₂) Rating

This graph shows the effect of your home on the environment in terms of carbon dioxide (CO_2) emissions. The higher the rating, the less impact it has on the environment.

Your current rating is **band D (61)**. The average rating for EPCs in Scotland is band D (59).

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

Top actions you can take to save money and make your home more efficient

Recommended measures	Indicative cost	Typical savings over 3 years
1 Low energy lighting	£100	£414.00
2 Solar water heating	£4,000 - £6,000	£174.00
3 Solar photovoltaic (PV) panels	£3,500 - £5,500	£1617.00

A full list of recommended improvement measures for your home, together with more information on potential cost and savings and advice to help you carry out improvements can be found in your recommendations report.

To find out more about the recommended measures and other actions you could take today to stop wasting energy and money, visit greenerscotland.org or contact Home Energy Scotland on 0808 808 2282.

THIS PAGE IS THE ENERGY PERFORMANCE CERTIFICATE WHICH MUST BE AFFIXED TO THE **DWELLING AND NOT BE REMOVED UNLESS IT IS REPLACED WITH AN UPDATED CERTIFICATE**

Summary of the energy performance related features of this home

This table sets out the results of the survey which lists the current energy-related features of this home. Each element is assessed by the national calculation methodology; 1 star = very poor (least efficient), 2 stars = poor, 3 stars = average, 4 stars = good and 5 stars = very good (most efficient). The assessment does not take into consideration the condition of an element and how well it is working. 'Assumed' means that the insulation could not be inspected and an assumption has been made in the methodology, based on age and type of construction.

Element	Description	Energy Efficiency	Environmental
Walls	Timber frame, as built, insulated (assumed)	★★★★☆	★★★★☆
Roof	Pitched, insulated (assumed) Roof room(s), ceiling insulated	***☆ ****☆	★★★★☆ ★★★★☆
Floor	Suspended, insulated (assumed)	—	_
Windows	Fully double glazed	****☆	★★★★☆
Main heating	Boiler and radiators, oil	★★★ ☆☆	★★★☆☆
Main heating controls	Programmer, room thermostat and TRVs	****☆	★★★ ☆
Secondary heating	Room heaters, dual fuel (mineral and wood)	—	_
Hot water	From main system	★★★ ☆☆	★★★☆☆
Lighting	Low energy lighting in 9% of fixed outlets	*****	****

The energy efficiency rating of your home

Your Energy Efficiency Rating is calculated using the standard UK methodology, RdSAP. This calculates energy used for heating, hot water, lighting and ventilation and then applies fuel costs to that energy use to give an overall rating for your home. The rating is given on a scale of 1 to 100. Other than the cost of fuel for electrical appliances and for cooking, a building with a rating of 100 would cost almost nothing to run.

As we all use our homes in different ways, the energy rating is calculated using standard occupancy assumptions which may be different from the way you use it. The rating also uses national weather information to allow comparison between buildings in different parts of Scotland. However, to make information more relevant to your home, local weather data is used to calculate your energy use, CO₂ emissions, running costs and the savings possible from making improvements.

The impact of your home on the environment

One of the biggest contributors to global warming is carbon dioxide. The energy we use for heating, lighting and power in our homes produces over a quarter of the UK's carbon dioxide emissions. Different fuels produce different amounts of carbon dioxide for every kilowatt hour (kWh) of energy used. The Environmental Impact Rating of your home is calculated by applying these 'carbon factors' for the fuels you use to your overall energy use.

The calculated emissions for your home are 40 kg CO₂/m²/yr.

The average Scottish household produces about 6 tonnes of carbon dioxide every year. Based on this assessment, heating and lighting this home currently produces approximately 7.1 tonnes of carbon dioxide every year. Adopting recommendations in this report can reduce emissions and protect the environment. If you were to install all of these recommendations this could reduce emissions by 1.3 tonnes per year. You could reduce emissions even more by switching to renewable energy sources.

CALADH PHORST, NEWTON STEWART, DG8 0JL 28 February 2024 RRN: 0160-2788-7120-2924-1831

Estimated energy costs for this home

Estimated energy costs for this nome			
	Current energy costs	Potential energy costs	Potential future savings
Heating	£4,578 over 3 years	£4,662 over 3 years	
Hot water	£576 over 3 years	£402 over 3 years	You could
Lighting	£1,050 over 3 years	£549 over 3 years	save £591
Т	otals £6,204	£5,613	over 3 years

These figures show how much the average household would spend in this property for heating, lighting and hot water. This excludes energy use for running appliances such as TVs, computers and cookers, and the benefits of any electricity generated by this home (for example, from photovoltaic panels). The potential savings in energy costs show the effect of undertaking all of the recommended measures listed below.

Recommendations for improvement

The measures below will improve the energy and environmental performance of this dwelling. The performance ratings after improvements listed below are cumulative; that is, they assume the improvements have been installed in the order that they appear in the table. Further information about the recommended measures and other simple actions to take today to save money is available from the Home Energy Scotland hotline which can be contacted on 0808 808 2282. Before carrying out work, make sure that the appropriate permissions are obtained, where necessary. This may include permission from a landlord (if you are a tenant) or the need to get a Building Warrant for certain types of work.

Becommended measures	Indicative cost	Typical saving	Rating after improvement		
Recommended measures	indicative cost	per year	Energy	Environment	
1 Low energy lighting for all fixed outlets	£100	£138	C 69	D 62	
2 Solar water heating	£4,000 - £6,000	£58	C 70	D 64	
3 Solar photovoltaic panels, 2.5 kWp	£3,500 - £5,500	£539	C 76	C 69	

Choosing the right improvement package

For free and impartial advice on choosing suitable measures for your property, contact the Home Energy Scotland hotline on 0808 808 2282 or go to www.greenerscotland.org.



About the recommended measures to improve your home's performance rating

This section offers additional information and advice on the recommended improvement measures for your home

1 Low energy lighting

Replacement of traditional light bulbs with energy saving bulbs will reduce lighting costs over the lifetime of the bulb, and they last many times longer than ordinary light bulbs. Low energy lamps and fittings are now commonplace and readily available. Information on energy efficiency lighting can be found from a wide range of organisations, including the Energy Saving Trust (http://www.energysavingtrust.org.uk/home-energy-efficiency/lighting).

2 Solar water heating

A solar water heating panel, usually fixed to the roof, uses the sun to pre-heat the hot water supply. This can significantly reduce the demand on the heating system to provide hot water and hence save fuel and money. Planning permission might be required, building regulations generally apply to this work and a building warrant may be required, so it is best to check these with your local authority. You could be eligible for Renewable Heat Incentive payments which could appreciably increase the savings beyond those shown on your EPC, provided that both the product and the installer are certified by the Microgeneration Certification Scheme (or equivalent). Details of local MCS installers are available at www.microgenerationcertification.org.

3 Solar photovoltaic (PV) panels

A solar PV system is one which converts light directly into electricity via panels placed on the roof with no waste and no emissions. This electricity is used throughout the home in the same way as the electricity purchased from an energy supplier. Planning permission might be required, building regulations generally apply to this work and a building warrant may be required, so it is best to check with your local authority. The assessment does not include the effect of any Feed-in Tariff which could appreciably increase the savings that are shown on this EPC for solar photovoltaic panels, provided that both the product and the installer are certified by the Microgeneration Certification Scheme (or equivalent). Details of local MCS installers are available at www.microgenerationcertification.org.

Low and zero carbon energy sources

Low and zero carbon (LZC) energy sources are sources of energy that release either very little or no carbon dioxide into the atmosphere when they are used. Installing these sources may help reduce energy bills as well as cutting carbon.

LZC energy sources present: There are none provided for this home

Your home's heat demand

In this section, you can see how much energy you might need to heat your home and provide hot water. These are estimates showing how an average household uses energy. These estimates may not reflect your actual energy use, which could be higher or lower. You might spend more money on heating and hot water if your house is less energy efficient. The table below shows the potential benefit of having your loft and walls insulated. Visit https://energysavingtrust.org.uk/energy-at-home for more information.

Heat demand	Existing dwelling	Impact of loft insulation	Impact of cavity wall insulation	Impact of solid wall insulation
Space heating (kWh per year)	14,419	N/A	N/A	N/A
Water heating (kWh per year)	2,335			

About this document

This Recommendations Report and the accompanying Energy Performance Certificate are valid for a maximum of ten years. These documents cease to be valid where superseded by a more recent assessment of the same building carried out by a member of an Approved Organisation.

The Energy Performance Certificate and this Recommendations Report for this building were produced following an energy assessment undertaken by an assessor accredited by Elmhurst (www.elmhurstenergy.co.uk), an Approved Organisation Appointed by Scottish Ministers. The certificate has been produced under the Energy Performance of Buildings (Scotland) Regulations 2008 from data lodged to the Scottish EPC register. You can verify the validity of this document by visiting www.scottishepcregister.org.uk and entering the report reference number (RRN) printed at the top of this page.

Assessor's name: Assessor membership number:	Mr. Ian Young EES/012603
Company name/trading name: Address:	J & E Shepherd 13 Albert Square
	Dundee
	DD1 1XA
Phone number:	01382 200454
Email address:	dundee@shepherd.co.uk
Related party disclosure:	No related party

If you have any concerns regarding the content of this report or the service provided by your assessor you should in the first instance raise these matters with your assessor and with the Approved Organisation to which they belong. All Approved Organisations are required to publish their complaints and disciplinary procedures and details can be found online at the web address given above.

Use of this energy performance information

Once lodged by your EPC assessor, this Energy Performance Certificate and Recommendations Report are available to view online at www.scottishepcregister.org.uk, with the facility to search for any single record by entering the property address. This gives everyone access to any current, valid EPC except where a property has a Green Deal Plan, in which case the report reference number (RRN) must first be provided. The energy performance data in these documents, together with other building information gathered during the assessment is held on the Scottish EPC Register and is available to authorised recipients, including organisations delivering energy efficiency and carbon reduction initiatives on behalf of the Scottish and UK governments. A range of data from all assessments undertaken in Scotland is also published periodically by the Scottish Government. Further information on these matters and on Energy Performance Certificates in general, can be found at www.gov.scot/epc.

Advice and support to improve this property

There is support available, which could help you carry out some of the improvements recommended for this property on page 3 and stop wasting energy and money. For more information, visit greenerscotland.org or contact Home Energy Scotland on 0808 808 2282.

Home Energy Scotland's independent and expert advisors can offer free and impartial advice on all aspects of energy efficiency, renewable energy and more.









Property address	Caladh Phorst Glenluce Newton Stewart DG8 0JL
Seller(s)	Tracy Powell-Choriton
Completion date of property questionnaire	26/02/2024

Note for sellers

- Please complete this form carefully. It is important that your answers are correct.
- The information in your answers will help ensure that the sale of your house goes smoothly. Please answer each question with as much detailed information as you can.
- If anything changes after you fill in this questionnaire but before the date of entry for the sale of your house, tell your solicitor or estate agent immediately.

Information to be given to prospective buyer(s)

1.	Length of ownership			
	How long have you owned the proper	ty?	2021	
2.	Council tax			
	Which Council Tax band is your prope	rty in?	F	
3.	Parking			
	What are the arrangements for parking at your property? (Please tick all that apply) • Garage			
	Allocated parking space	No		
	• Driveway	Yes		
	Shared parking	No		
	On street	No		
	Resident permit	No		
	Metered Parking	No		
	Other (please specify):			
4.	Conservation area			
	Is your property in a designated Cons special architectural or historical inte which it is desirable to preserve or en	rest, the character or appear		

5.	Listed buildings		
	Is your property a Listed Building, or contained within one (that is a building recognised and approved as being of special architectural or historical interest)?	No	
6.	Alterations/additions/extensions		
а.	(i) During your time in the property, have you carried out any structural alterations, additions or extensions (for example, provision of an extra bath/shower room, toilet, or bedroom)?	No	
	If you have answered yes, please describe below the changes which you have made:		
	(ii) Did you obtain planning permission, building warrant, completion certificate and other consents for this work?		
	If you have answered yes, the relevant documents will be needed by the purchaser and you should give them to your solicitor as soon as possible for checking.		
	If you do not have the documents yourself, please note below who has these documents and your solicitor or estate agent will arrange to obtain them:		
b.	Have you had replacement windows, doors, patio doors or double glazing installed in your property?	No	
	If you have answered yes, please answer the three questions below:		
	(i) Were the replacements the same shape and type as the ones you replaced?		
	(ii) Did this work involve any changes to the window or door openings?		
	(iii) Please describe the changes made to the windows doors, or patio doors (with approximate dates when the work was completed):		
	Please give any guarantees which you received for this work to your solicitor or estate agent.		
7.	Central heating		
а.	Is there a central heating system in your property? (Note: a partial central heating system is one which does not heat all the main rooms of the property — the main living room, the bedroom(s), the hall and the bathroom).	Yes	
	If you have answered yes or partial – what kind of central heating is there? (Examples: gas-fired, solid fuel, electric storage heating, gas warm air).		
	Oil		

	i) When was your central heating system or partial central heating system installed?			
	2005			
	(ii) Do you have a maintenance contract for the central heating system?			No
	If you have answered yes, please give details of the company with which you have a maintenance contract:			
	(iii) When was your maintena (Please provide the month ar		d?	
8.	Energy Performance Certificate			
	Does your property have an than 10 years old?	Energy Performance Certifi	cate which is less	Yes
9.	Issues that may have affected your property			
a.	Has there been any storm, flood, fire or other structural damage to the property while you have owned it?		No	
	If you have answered yes, is the damage the subject of any outstanding insurance claim?			
b.	Are you aware of the existen		perty?	No
10.	Services			
a.	Please tick which services are connected to your property and give details of the supplier:			
	Services	Connected	Supplier	
	Gas or liquid petroleum gas	No		
	Water mains or private water supply	Yes	Scottish Water	
	Electricity	Yes	Scottish Power	
	Mains drainage	No		
	Telephone	Νο		

	Cable TV or satellite	No	
	Broadband	No	
b.	Is there a septic tank system at your property?		Yes
	If you have answered yes, please answer the two questions below:		
	(i) Do you have appropriate consents for the discharge from your septic tank?		tic Yes
	(ii) Do you have a maintenance contract for your septic tank?		No
	If have answered yes, details of the company with which you have a maintenance contract:		
11.	Responsibilities for share	ed or common areas	
а.	Are you aware of any responsibility to contribute to the cost of anything used jointly, such as the repair of a shared drive, private road, boundary, or garden area?		vthing No
	If you have answered ye	<u>es</u> , please give details:	
b.	Is there a responsibility to contribute to repair and maintenance of the roof, common stairwell or other common areas?		the No
	If you have answered ye	<u>es</u> , please give details:	
с.	Has there been any major repair or replacement of any part of the roof during the time you have owned the property?		No
d.	Do you have the right to walk over any of your neighbours'property — for example to put out your rubbish bin or to maintain your boundaries?		/ — No
	If you have answered ye	es, please give details:	
е.		do any of your neighbours have the right to , for example to put out their rubbish bin o es?	
	If you have answered ye	<u>es</u> , please give details:	
f.	your property? (public r	, is there a public right of way across any p ight of way is a way over which the public r not the land is privately-owned.)	
	If you have answered ye		

12. Charges associated with the property			
a.	Is there a factor or property manager for your property?		
	If you have answered yes, please provide the name and address, and give details of any deposit held and approximate charges:		
b.	Is there a common buildings insurance policy?	No	
	If you have answered yes, is the cost of the insurance included in monthly/annual factor's charges?		
с.	Please give details of any other charges you have to pay on a regular basis for the upkeep of common areas or repair works, for example to a residents' association, or maintenance or stair fund.		
13.	Specialist work		
а.	As far as you are aware, has treatment of dry rot, wet rot, damp or any other specialist work ever been carried out to your property?	No	
	If you have answered yes, please say what the repairs were for, whether you carried out the repairs (and when) or if they were done before you bought the property.		
b.	As far as you are aware, has any preventative work for dry rot,wet rot, or damp ever been carried out to your property?	No	
	If you have answered yes, please give details:		
C.	If you have answered yes to 13(a) or (b), do you have any guarantees relating to this work?		
	If you have answered yes, these guarantees will be needed by the purchaser and should be given to your solicitor as soon as possible for checking. If you do not have them yourself <u>please write below who</u> <u>has these documents</u> and your solicitor or estate agent will arrange for them to be obtained. You will also need to provide a description of the work carried out. This may be shown in the original estimate.		
	Guarantees are held by:		
14.	Guarantees		
a.	Are there any guarantees or warranties for any of the following?		
	(i) Electrical work	No	
	(ii) Roofing	No	
	(iii) Central heating	No	
	(iv) National House Building Council (NHBC)	No	

	(v) Damp course	Don't know	
	(vi) Any other work installations? (for example, cavity wall installation, underpinning, indemnity policy)	No	
b.	If you have answered 'yes' or 'with title deeds', please give details of the work o installations to which the guarantee(s) relate(s):		
с.	Are there any outstanding claims under any of the guarantees listed above? <u>If you have answered yes,</u> please give details:	No	
15.	Boundaries		
	So far as you are aware, has any boundary of your property been moved in thelast 10 years?	No	
	If you have answered yes, please give details:		
16.	Notices that affect your property		
	In the past three years have you ever received a notice:		
а.	advising that the owner of a neighbouring property has made a planning application?	No	
b.	that affects your property in some other way?	No	
C.	that requires you to do any maintenance, repairs or improvements to your property?	No	
	If you have answered yes to any of a-c above, please give the notices to your solicitor or estate agent, including any notices which arrive at any time before the date of entry of the purchaser of your property.		

Declaration by the seller(s)/or other authorised body or person(s)

I/We confirm that the information in this form is true and correct to the best of my/our knowledge and belief

Name(s): Tracy Chorlton

Date: 26/02/2024



Residential

Home Report

Mortgage & Re-Mortgage Valuation Home & Flat Buyer Report Energy Performance Certificate (EPC) Private Sale Valuation Inheritance Tax Valuation Capital Gains Tax Valuation Separation Valuation **Driveby Valuation** Desktop Valuation New Build, Development & Plot Valuation Extension & Alteration Valuation Portfolio Valuation **Rental Valuation Expert Witness Report** Council Tax Appeal **Bespoke Condition Report**

Commercial

Commercial Valuation Commercial Agency Acquisitions & Disposals Commercial Lease Advisory Rent Reviews Asset Management Project Consultancy Development Appraisals Rating Commercial Property Auctions Property Management Professional Services Licensed Trade / Leisure

Glasgow West End

A 0141 353 2080

A 01475 730717

▲ 01698 897548

Inverness ▲ ▲ 01463 712239

A 01563 520318

Greenock

Hamilton

Kilmarnock

Property & Construction

Quantity Surveying Building Surveying Project Management Dispute Resolution Support Services Principal Designer Clerk of Works Commercial EPC Fire Engineering Health & Safety Management Employer's Agent Energy Department Housing Services Development Monitoring Mediation Services



 Dumfries

 ▲ 1387 264333

 Dundee

 ▲ 01382 200454

 ▲ 01382 20054

 ▲ 01382 720699

 Dunfermline

 ▲ 01383 722337

 ▲ 01383 731841

 ▲ 01355 248535

Edinburgh ▲ 0131 2251234 ▲ 0131 557 9300





Elgin ▲ 01343 553939

▲ 01324 635 999

Fraserburgh ▲ 01346 517456

A 01896 750150

▲ ▲ 0141 331 2807

Galashiels

Glasgow

Falkirk

Livingston ▲ 01506 416777 Montrose ▲ 01674 676768 Motherwell ▲ 01698 252229 Musselburgh ▲ 0131 653 3456 Oban ▲ 01631 707 800 Paisley ▲ 0141 889 8334 Perth ▲ 01738 638188 ▲ 01738 631631 Peterhead ▲ 01779 470766 St Andrews ▲ 01334 477773 ▲ 01334 477773 ▲ 01334 4774669 Saltcoats ▲ 01294 464228 Stirling ▲ 01786 450438 ▲ 01786 474476

www.shepherd.co.uk
 www.hardies.co.uk